

Goxhill Pothole Repair Survey 2019

On the 21st June 2019 a survey was carried out looking at the repairs that have been completed so far by NLC. Photographs were taken and below you will see before and after pictures of the repairs with a description of their location.

NLC FS118883317 – Enquiry 287605

Chapelfield Road between junction with East Marsh Lane and Spring Farm, large sections of road cracking due to subsidence with vegetation growing in the cracks and potholes.



Several areas identified at this location but this was the only repair work carried out.

NLC FS118883612 – Enquiry 287606

Chapelfield Road located in front of Spring Farm, road is subsiding on the inside of the bend and there are numerous potholes.



Photos show the before and after pictures of the 'repairs' carried out. The longevity of these repairs is questionable.





NLC FS118883932 – Enquiry 287607

Chapelfield Road between Spring Farm and Marshland Farm, large areas of the edge of the road cracking due to subsidence and several potholes identified.



Several areas identified at this location but this was the only repair work carried out.



These two pictures show areas where no repairs have been carried out.

NLC FS118886651 – Enquiry 287618

Elm Lane between White Bungalow and the junction with North End, this section of road has numerous potholes with previous been filled in but the repairs are now breaking down.



Only small parts of the road have been repaired – the longevity of these repairs is questionable.



NLC FS118887466 Enquiry – 287622

Mill Lane on the bends outside Seven Trees and Tara there are large potholes and cracks in the road.



Only small parts of the road have been repaired – the longevity of these repairs is questionable.



NLC FS118887723 Enquiry – 287624

Mill Lane between Tara and the junction with Ferry Road various potholes and cracks in the road identified.



Several potholes filled in, as you can see from the pictures the longevity of the repair again is questionable.



NLC FS119711438 – Enquiry 287778

Chestnut Way junction with Ferry Road the surface of the road is breaking down causing cracks and potholes.



Potholes repaired for now, road surfacing is still breaking down with new potholes forming.

NLC FS120366863 – Enquiry 287962

Manor Lane junction with Ferry Road the surface of the road is breaking down causing cracks and potholes.



Potholes repaired for now, road surfacing is still breaking down with new potholes forming the longevity of repair is questionable.



NLC FS120775743 – Enquiry 288079 and NLC FS120252380 – Enquiry 287929

Ferry Road between Ferry Farm and Rowland Hill Farm there are several cracks in the road and potholes.





Approximately a 300-metre section of Ferry Road has had a new road surface put down.

NLC FS120776178 – Enquiry 288081

Ferry Road entrance to Totney Hill Farm surface breakdown causing cracking and potholes to develop.



I have been informed that the repairs here are complete, as you can see from the pictures that no repairs have been complete.

NLC FS120243196 – Enquiry 287915

Abbeygarth Villas (10-19) road has numerous potholes.



Majority of potholes filled in.



NLC FS120257202 – Enquiry 287939

Greengate Lane the whole length of this lane is covered in potholes, some of which have previously been repaired but now the repair is also breaking down.



Some potholes have been filled in but as you can see from the pictures more repairs will be required in the near future.



NLC FS120773727 – Enquiry 288069

Horsegate Field Road junction with East Marsh Lane, surface cracking is causing potholes to develop.



Several potholes at this junction have been filled but as you can see from the pictures the longevity of these repairs are questionable.

NLC FS120773923 – Enquiry 288070

Horsegate Field Road from 20-metres from the junction with East Marsh Lane to the crossroads with Ruards Road, several cracks in the road with vegetation growing out of and potholes on the edge of the road.




This was the only repair carried out on this stretch of road.



Small sample of areas were a repair has not been carried out.

NLC FS120774148 – Enquiry 288071

Horsegate Field Road between the crossroads with Ruards Road and the entrance to Rosbrook Way, several potholes in the road and on the edge of the road identified.



As you can see from the number of past repairs, this section of road is prone to potholes – longevity of this repair questionable.



NLC FS120772867 – Enquiry 288065

Howe lane between the entrance to The Bridles and Horsegate Field Road, several potholes identified.



Some repairs carried out.



NLC FS120371158 – Enquiry 287980

Howe Lane between the Level Crossing and the junction with Thornton Road, the road is cracked in several places leading to potholes and uneven surface.



As you can see from the pictures only small areas have been repaired.



NLC FS120239920 – Enquiry 287910

South End junction with Thorn Lane several cracks and potholes have developed.



Small repairs carried out – longevity of repair questionable.



NLC FS120242241 – Enquiry 287914

Church Side from the Level Crossing to Hallands Field House the edge of the road is subsiding causing cracking and potholes to develop.



Small repairs carried out – longevity of repair questionable.



As you can see from the work carried out so far the longevity of the repairs is questionable. Apart from the 300-metre section of work which has already been carried out on Ferry Road, and the current work being carried out between Elm Lane and the National speed limit sign heading out of the village. This work I believe is being partly/majority funded by the National Grid.

These repairs I have conveyed in this report are only 20 of the 134 request I sent in to NLC, I do not know when/if anymore repair work is going to be carried out.